D3213-041  Door Assembly  1/29/2013	4.4.4.	Accept	*N900	0.40	400					
1/30/2013 Req'd Qty: 1.00	ماد 4 ماد			1 141 1	1()(	)*	Setup	Start Stop	I VI.	S1* S2*
RMA RA111471 - REWA	*1* *1* درح		Cust Item I		AR001					
Process Plan:	Date:\\( \) - 2 - \\\ Date:\	Tooling: SPC (Y/N):		ite:			Run	Start Stop	171	R1* R2*
Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	t Rej Qty		Reject Number	Insp. Stamp
Revision Nbr										
В		0.00				<del></del>				
PART IS G	OOD	13 B	1.125			<del></del>				
Identify as per dwg & Si  Memo	tock Location	0.00				18				3-3
QC21- Final Inspection  Memo	- Work Order Release	0.00						3/	起   1	34
	INSPECT F PART IS G ID AND ST Identify as per dwg & St  Memo  QC21- Final Inspection	INSPECT RA 111471 D3213-041 X  PART IS GOOD ID AND STOCK UNDER NEW BAT  Identify as per dwg & Stock Location  Memo  QC21- Final Inspection - Work Order Release	INSPECT RA 111471 D3213-041 X 1 B#92832  PART IS GOOD ID AND STOCK UNDER NEW BATCH NUMBER  Identify as per dwg & Stock Location 0.00  Memo 0.00  QC21- Final Inspection - Work Order Release 0.00	PART IS GOOD ID AND STOCK UNDER NEW BATCH NUMBER  Identify as per dwg & Stock Location 0.00  Memo 0.00  QC21- Final Inspection - Work Order Release 0.00	INSPECT RA 111471 D3213-041 X 1 B#92832  PART IS GOOD ID AND STOCK UNDER NEW BATCH NUMBER  Identify as per dwg & Stock Location 0.00  Memo 0.00  QC21- Final Inspection - Work Order Release 0.00	PART IS GOOD ID AND STOCK UNDER NEW BATCH NUMBER  Identify as per dwg & Stock Location  Memo  O.00  QC21- Final Inspection - Work Order Release  0.00	PART IS GOOD ID AND STOCK UNDER NEW BATCH NUMBER  Identify as per dwg & Stock Location  Memo  O.00  QC21- Final Inspection - Work Order Release  0.00	INSPECT RA 111471 D3213-041 X 1 B#92832  PART IS GOOD ID AND STOCK UNDER NEW BATCH NUMBER  Identify as per dwg & Stock Location 0.00  Memo 0.00  OC21- Final Inspection - Work Order Release 0.00	INSPECT RA 111471 D3213-041 X 1 B#92832  PART IS GOOD ID AND STOCK UNDER NEW BATCH NUMBER  Identify as per dwg & Stock Location 0.00  Memo 0.00  OC21- Final Inspection - Work Order Release 0.00	INSPECT RA 111471 D3213-041 X 1 B#928 2 16  PART IS GOOD ID AND STOCK UNDER NEW BATCH NUMBER  Identify as per dwg & Stock Location 0.00  Memo 0.00  QC21- Final Inspection - Work Order Release 0.00

**Picklist Print** 

Monday, February 11, 2013 3:31:47 PM

Page 1

Work Order ID:

96495

Parent Item:

D3213-041

Parent Item Name:

Door Assembly

Start Date: 1/29/2013

Required Date: 1/30/2013

Start Oty: 1.00

Required Oty: 1.00

Comments:

IPP Rev: A

New Issue 05-11-17 17:27

	111 107.21 1107	V 135UC 05-11-17	1 / . 4 /										
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3213-041		Manufactured	No				Each	1.0000		1			

Door Assembly

 Location
 Loc Qty
 Loc Code

 ST211
 1

82832

1 × 92832 1 × 92832

## RA111471 D350-567-117 B95140

Received @ Dart January 23<sup>rd</sup>, 2013 Inspected@ Dart January 25<sup>th</sup>, 2013

Customer: MT. WEST HELICOPTERS Customer Contact: BRAIN HUSTON Shipped from: CARLSBAD CA, USA

## Instructions for RA 111471 D350-567-117 B95140 (NCR 13-2219)

- Customer returned "D" parts only
  - o Returned D3210-1 B91696
  - o Returned D3213-041 B92832
  - o . Returned D3211-1 B91755
  - o Returned D3212-1 B90186
- All parts can go back in to stock under NEW BATCH #'s

Time Estimate = 1 HOUR ONLY (stores)

Departments Required: Stores (restocking)

Pictures Attached = NO

OTY INSPECTED =

## THIS INSTRUCTION SHEET MUST BE ATTACHED TO THE RESTOCKING WORK ORDER AT ALL TIMES!!!!